

Wednesday, March 30, 2022 | Mileage: 0 km

Sequence	Action	Start Time	End Time	Resource ID	Technician
1	PTS : VIN 1FTFW1ED5MFB13620	12:52 PM	12:52 PM		
2	PTS : FSA : 22S12	12:52 PM	12:52 PM		
3	PTS : Workshop Manual : 2021 F-150	12:53 PM	12:53 PM	SM2	
4	PTS : Workshop Manual : 418-00A Contoller Area Network (CAN) Module Communications Network::Removal and Installation::Gateway Module A (GWM)	12:53 PM	12:53 PM	G2198261	
5	PTS : Workshop Manual : 418-00A Contoller Area Network (CAN) Module Communications Network::Removal and Installation::Gateway Module A (GWM)	12:53 PM	12:53 PM	G2198261	
6	PTS : Workshop Manual : 501-12 Instrument Panel and Console::Removal and Installation::Glove Compartment	12:55 PM	12:55 PM	G2158779	
7	PTS : Workshop Manual : 415-00 Information and Entertainment System - General Information::Removal and Installation::Instrument Panel Center Speaker	12:55 PM	12:55 PM	G2169390	
8	PTS : Workshop Manual : 501-12 Instrument Panel and Console::Removal and Installation::Floor Console	12:56 PM	12:56 PM	G2158778	
9	PTS : Workshop Manual : 501-12 Instrument Panel and Console::Removal and Installation::Floor Console	12:56 PM	12:56 PM	G2158778	
10	PTS : Workshop Manual : 501-10A Front Seats::Removal and Installation::Front Seat	12:56 PM	12:56 PM	G2175112	
11	PTS : TSB : 22-2117 2021 Mustang Mach-E/F-150 - Ford Power-Up Software Update Failure Message	12:57 PM	12:57 PM		
12	PTS : TSB : 22-2060	12:59 PM	12:59 PM		
13	PTS : TSB : 22-2060	1:00 PM	1:00 PM		
14	PTS : TSB : 22-2123	1:00 PM	1:00 PM		
15	Network Test	1:55 PM	1:55 PM	JavaNTest	
16	Datalogger	1:56 PM	1:58 PM	G1906396	
17	Self Test	1:59 PM	5:42 PM	G1906412	
18	PTS : VIN 1FTFW1ED5MFB13620	2:00 PM	2:00 PM		
19	PTS : Workshop Manual : 2021 F-150	2:00 PM	2:00 PM	SM2	
20	PTS : Workshop Manual : 415-00 Information and Entertainment System - General Information::Diagnosis and Testing::Information and Entertainment System	2:00 PM	2:00 PM	G2162374	
21	PTS : Diagnostic G2162374:PINPOINT TEST AO: MODULE CONFIGURATION FAULT	2:00 PM	2:00 PM		
22	PTS : Workshop Manual : 418-01A Module Configuration::General Procedures::Module Programming	2:01 PM	2:01 PM	G2175464	
23	Programmable Module Installation (PMI)	2:02 PM	3:50 PM	G2132500	
24	Programmable Module Installation (PMI)	3:50 PM	5:41 PM	G2132500	
25	Gateway Module A (GWM) Configuration	5:19 PM	5:20 PM	G2132533	
26	Programmable Module Installation (PMI)	5:21 PM	5:22 PM	G2132532	
27	Programmable Module Installation (PMI)	5:22 PM	5:24 PM	G2132532	
28	Programmable Module Installation (PMI)	5:24 PM	5:26 PM	G2132532	
29	PTS : TSB : 22-2117 2021 Mustang Mach-E/F-150 - Ford Power-Up Software Update Failure Message	5:30 PM	5:30 PM		
30	Self Test	5:42 PM	5:46 PM	G1906412	
31	Module Update Repair	5:47 PM	5:47 PM	G2303216	
32	Network Test	5:48 PM	5:49 PM	JavaNTest	
33	Module Update Repair	5:50 PM	5:51 PM	G2303216	
34	Self Test	5:51 PM	5:51 PM	G1906412	
35	Network Test	6:04 PM	6:04 PM	JavaNTest	
36	Self Test	6:05 PM	6:29 PM	G1906412	
37	Trailer Module (TRM) Software Update	6:22 PM	6:25 PM	G2194218	