

Last Vehicle Status Update: April 12, 2024 06:07 PM

*Note: Do not use as a pressure gauge

Refresh

Odometer



69 Miles

High Voltage Battery



Battery State of Charge : 72%

Battery Range : 205 Miles

Tire Pressure (PSI)*

40  39

40  39



Recommended Tire Pressure(cold)

Front : 36 | Rear : 36

February 2024

Sun	Mon	Tue	Wed	Thu
				1
4	5	6	7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

March 2024

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11	12	13	14
17	18 	19	20	21
24	25	26 	27	28
31				

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15	16	17	18
21	22	23	24	25
28	29	30		

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date | Time | Odometer

Event Description



Module

DTC

: FT : SB

TSB/GSB/SSM



Send to Search

Description

Time : 06:41 PM

Odometer :

70 mi

APIM		U0232: 00 : 08	<input type="checkbox"/>  Lost Communication With Side Obstacle Detection Control Module 'A'
APIM		U0208: 00 : 08	<input type="checkbox"/>  Lost Communication With Seat Control Module 'A'
APIM		U0256: 00 : 08	<input type="checkbox"/>  Lost Communication With Front Controls Interface Module 'A'
APIM		U0159: 00 : 08	<input type="checkbox"/>  Lost Communication With Parking Assist Control Module 'A'
APIM		U0100: 00 : 08	<input type="checkbox"/>  Lost Communication With ECM/PCM 'A'
APIM		U0212: 00 : 08	<input type="checkbox"/>  Lost Communication With Steering Column Control Module
APIM		U0233: 00 : 08	<input type="checkbox"/>  Lost Communication With Side Obstacle Detection Control Module 'B'
APIM		U0214: 00 : 08	<input type="checkbox"/>  Lost Communication With Remote Function Actuation Module
APIM		U023B: 00 : 08	<input type="checkbox"/>  Lost Communication With Image Processing Module B
PACM		U0100: 00 : 08	<input type="checkbox"/>  Lost Communication With ECM/PCM 'A'
APIM		U0238: 00 : 08	<input type="checkbox"/>  Lost Communication With Digital Audio Control Module 'D'
APIM		U020C: 00 : 08	<input type="checkbox"/>  Lost Communication with Wireless Accessory Charging Module 'A'
ABS		U3001: 68 : 2B	<input type="checkbox"/>  Control Module Improper Shutdown Performance
PACM		U0140: 00 : 08	<input type="checkbox"/>  Lost Communication With Body Control Module
APIM		U0121: 00 : 08	<input type="checkbox"/>  Lost Communication With Anti-Lock Brake System (ABS) Control Module 'A'
APIM		U0151: 00 : 08	<input type="checkbox"/>  Lost Communication With Restraints Control Module
IPC		U013F: 82 : 08	<input type="checkbox"/>  Lost Communication With Pedestrian Alert Control Module
APIM		U0184: 00 : 08	<input type="checkbox"/>  Lost Communication With Radio
APIM		U0155: 00 : 08	<input type="checkbox"/>  Lost Communication With Instrument Panel Cluster (IPC) Control Module
APIM		U0198: 00 : 08	<input type="checkbox"/>  Lost Communication With Telematic Control Module 'A'
APIM		U0293: 00 : 08	<input type="checkbox"/>  Lost Communication With Hybrid/EV Powertrain Control Module 'A'
APIM		U0140: 00 : 08	<input type="checkbox"/>  Lost Communication With Body Control Module

SSM

Time : 05:43 PM

Odometer :

67 mi

★	ABS		U3001: 68 : 2B
★	APIM		U0140: 00 : 08
★	APIM		U0293: 00 : 08
★	APIM		U0198: 00 : 08
★	APIM		U0155: 00 : 08
★	APIM		U0184: 00 : 08
★	APIM		U0151: 00 : 08
★	APIM		U0121: 00 : 08
★	APIM		U020C: 00 : 08
★	APIM		U0238: 00 : 08
★	APIM		U023B: 00 : 08
★	APIM		U0214: 00 : 08
★	APIM		U0233: 00 : 08
★	APIM		U0212: 00 : 08
★	APIM		U0100: 00 : 08
★	APIM		U0159: 00 : 08
★	APIM		U0256: 00 : 08
★	APIM		U0208: 00 : 08
★	APIM		U0232: 00 : 08
★	IPC		U013F: 82 : 08
★	PACM		U0140: 00 : 08
★	PACM		U0100: 00 : 08

SSM

- ⚠ Control Module Improper Shutdown Performance
- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With Telematic Control Module 'A'
- ⚠ Lost Communication With Instrument Panel Cluster (IPC) Control Module
- ⚠ Lost Communication With Radio
- ⚠ Lost Communication With Restraints Control Module
- ⚠ Lost Communication With Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lost Communication With Wireless Accessory Charging Module 'A'
- ⚠ Lost Communication With Digital Audio Control Module 'D'
- ⚠ Lost Communication With Image Processing Module B
- ⚠ Lost Communication With Remote Function Actuation Module
- ⚠ Lost Communication With Side Obstacle Detection Control Module 'B'
- ⚠ Lost Communication With Steering Column Control Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Parking Assist Control Module 'A'
- ⚠ Lost Communication With Front Controls Interface Module 'A'
- ⚠ Lost Communication With Seat Control Module 'A'
- ⚠ Lost Communication With Side Obstacle Detection Control Module 'A'
- ⚠ Lost Communication With Pedestrian Alert Control Module
- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With ECM/PCM 'A'

March 18, 2024

Select All

Time : 03:20 PM

Odometer :

60 mi

★ DCACA | U0140: 00 : 28

★ SOBDMC | P2DA6: 00 : 2C

CMR | B15E1: 97 : 08

SSM

⚠ Lost Communication With Body Control Module

⚠ Coolant Heater 'A' Over Temperature

⚠ Driver Side LED

February 16, 2024

Select All

Time : 11:30 AM

Odometer :

54 mi

CMR | B15E1: 97 : 08

SSM

SOBDMC | P2DA6: 00 : 28

⚠ Driver Side LED

⚠ Coolant Heater 'A' Over Temperature