



SSM 52679 2022-2023 F-150 Lightning - Powertrain Module Reprogramming In The FDRS Temporarily Suspended

Some 2022-2023 F-150 Lightning vehicles may require module reprogramming in the Ford Diagnosis and Repair System (FDRS) scan tool to certain powertrain modules such as:

- powertrain control module (PCM)
- battery energy control module (BECM)
- anti-lock brake system (ABS) module
- secondary on-board diagnostic control module C (SOBDMC)
- secondary on-board diagnostic control module A (SOBDM)
- secondary on-board diagnostic control module B (SOBDMB)
- generic function module 2 (GFM2)

Module reprogramming in the FDRS has been temporarily suspended for these powertrain modules. A solution for this condition is expected in August 2024. Monitor Professional Technician System (PTS), OASIS, and Field Service Action (FSA) landing pages for additional information and schedule service appointments for customers once the repair becomes available.