



SSM 51352 2021-2022 F-150 - False Alarm Activation With A Trailer Connected And/Or DTC U0143:87 Stored In The Trailer Module (TRM) After TSB 22-2122

Some 2021-2022 F-150 vehicles may still have a false alarm activation with a trailer connected and/or diagnostic trouble code (DTC) U0143:87 stored in the TRM after technical service bulletin (TSB) 22-2122 was completed. This was due to a software release issue. To correct the condition download and run the TRM configuration application in the Ford Diagnosis and Repair System (FDRS). For claiming use 12651D4 in section 10 of the service labor time standard (SLTS) manual.